Project No Name: Address:	Location E2SW4 & W2SE4 Sec. 20 T 12 N. R 14 E. of the 6th P.M., Cass County, Nebraska
	RVEYOR'S CERTIFICATE
I hereby certify that this plat, map, supervision and that I am a duly Re	survey or report was made by me or under my direct personal gistered Land Surveyor under the laws of the State of Nebraska.  MARKING THE FUTURE
founded a while back	
LEGAL DESCRIPTION:	Lot 14, (Replatted)- Happy Hill Subdivision, located in the E1/2 of the SW14 and the W12 of the
15	SEV4 of Section 20-TI2N-RI4E of the 6th P.M.
(replatted)	Cass County, Nebraska Found 5/8"
	rebar
Found 2" N 68°55'58" E. M=18.08' P=18.51'	S ( 1) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Found 2" pt pipe	Found 5/8" rebar
	15 82 mazon n
	Set drill hole w/wings in concrete drive
	Found 5/8" rebar
	Edge of concrete drive is 0.90'
	inside Lot line
( <del>pa</del>	replatted) **
j 5	S N
53.	EY RECORD REPOSITORY 13
N N	RECEIVED
	JAN 0 9 2007 250
Count	795-156
EBRASK4 5/8" rebar	Found North 5/8" rebar  P=230.00'  Scale 1" - 100'
REGISTERES.	( NOT A PART OF THIS SURDIVISION ) C=Set 5/8"x24" rebar
LS-420 9555	### = Found 5/8" rebar  P = Plat Distance
SURVE DE LOS	M = Measured distance R = Record distance C = Computed distance
A STATE OF THE STA	Signed this 17th day of December A.D.,2006.
S 00°12′12″ W	Charles P. John
Found 2" S 89°48'38" W Found 2" open pipe P=66.00 open pipe	Surveyor's License No. L.S. 420 Jordan Surveying Co.
Disc 003	Plattsmouth, Nebraska Prinsed in a State of America MMV